




KONICA MINOLTA

# キャリングケースRA-A213の取り扱い

RA-A213は、非接触3次元デジタイザ RANGE7専用のキャリングケースです。本ケースはRANGE7本体・付属品の保管および運搬を目的に設計されています。必ず「収納方法」「使用上の注意」をよく読んでからご使用ください。RANGE7は精密機器のため、衝撃・振動を与えないでください。

## 収納方法

\*下図はRANGE7および付属品の収納例です。




RANGE7本体を本ケースに収納するときは

- USBケーブル、ACアダプタコードなど、すべてのケーブル類を取り外してください。
- レンズにはレンズキャップを取り付けてください。
- 本体の回りの隙間には、何も入れないでください。

## 使用上の注意

非接触3次元デジタイザ RANGE7は精密測定器です。本ケースに収納して移動、保管などされる場合は、衝撃や振動を極力おさえるようご注意ください。

- 落としたり、衝撃を与えたりしないでください。
- 本ケースは防水ケースではありませんので、水に濡らしたりしないでください。
- ケースを横にして置く場合、ハンドルのある側を下にして置いてください。
- 収納後ケースを開けるときは、ハンドルのある側を下にして、横置きにしてから開けてください。



ハンドル



KONICA MINOLTA

# Handling of Carrying Case RA-A213


Carrying Case RA-A213 is an exclusive case for Non-Contact 3D Digitizer RANGE7 and its accessories. Before using this case, please read following "How to use" and "Notes on Use".

This Carrying Case is designed for storage and transportation.

RANGE7 is a precision measuring instrument. Please take care to minimize shock or vibration as follows.

## How to use (Storage method)

\* This is an example of storing RANGE7 and accessories.




When storing the RANGE7...

- Remove any cables from the RANGE7.
- Attach the lens cap to the lens.
- Do not put anything in around the RANGE7.

## Notes on Use

RANGE7 is a precision measuring instrument. When moving or storing the instrument, please take care to minimize shock or vibration as follows:

- Do not drop the case or subject it to strong shock or vibration.
- The case is not waterproof. Do not allow liquids to be spilled or splashed on the case.
- When placing the case horizontally, be sure that the side with handles is the downside.
- When opening the case, be sure that the side with handles is the downside, and then open the side with no handle.



**Handle**